

**NOTICE OF FIRE SAFETY INSPECTION  
OREGON STATE UNIVERSITY**



Facility Inspected: DRYDEN HALL  
 Date Inspected: 7-Nov-06  
 Reinspect Date: 19-Dec-06  
 Reinspect Time: 9:00 A.M.  
 EH&S Rep: Dan

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 766-6903. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@ci.corvallis.or.us*

**NOTE** **Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

\* *Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible groups and begin corrective action as soon as possible.

Facility Services Priority Codes:

- Priority 1 – (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be
- Priority 2 – (p2) items should be corrected within the five-week period before the
- Priority 3 – (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Andrew Gray at extension 7-7651 or [andrew.gray@orst.edu](mailto:andrew.gray@orst.edu). If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description	Code Reference
FS-2	South Fire Escape	Cut vegetation back to provide adequate and safe clearance to public way.	
FS-2	Stdpipes	Cap all standpipe connections	
FS-2	Hallways	Provide approved illuminated EXIT signs with battery back up to identify central stairwell	
DEPT	3rd Flr. Stairwell Landing	Re move items from stairwell. Keep clear at all times.	
DEPT	Windows to fire escpae	Have Facility Services test the operation of every window that serves the fire escpae. Also insure the windows can be unlocked from floor level without having to stand on something to reach the locking mechanism.	
DEPT	Left of 309	Remove refrigerator out of hallway. Hallways shall not be used for storage at any time.	
RECY	3rd Flr. Hallwa	Remove combustible recycling bags from hallway.	

Responsible Party	Area	Description	Code Reference
DEPT	Nr. 301	Remove items from hallway. Hallways shall not be used for storage at any time.	
FS-2	Rm. 314	Replace cover to attic access	
FS-2	Rm. 311	Replace wired glass with standard breakable glass for egress.	
RECY	Left of 207	Remove combustible recycling bags from hallway.	
DEPT	Rm. 205	Label all chemical containers as to plain language contents/hazards.	
DEPT	Nr. 205	Remove items from hallway. Hallways shall not be used for storage at any time.	
DEPT	Rm. 201	Label all chemical containers as to plain language contents/hazards. Cap all containers not located under hood.	
DEPT	1st Flr.	Remove items from hallway. Hallways shall not be used for storage at any time.	
DEPT	Rm. 107	Remove all glass chemical containers from floor.	
FS-2		Replace coverplate to outlet.	
DEPT	Rm. 108A	Plug all power strips directly into outlet. Do not chain them together.	
DEPT	Rm. 102	Secure all high pressure cylinders.	