

**NOTICE OF FIRE SAFETY INSPECTION
OREGON STATE UNIVERSITY**



Facility Inspected: FAIRBANKS HALL & ANNEX
 Date Inspected: 7-Dec-06
 Reinspect Date: 16-Jan-07
 Reinspect Time: 9:00 AM
 EH&S Rep: BRANDON

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 766-6903. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@ci.corvallis.or.us*

NOTE **Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

* *Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible groups and begin corrective action as soon as possible.

Facility Services Priority Codes:

- Priority 1 – (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be
- Priority 2 – (p2) items should be corrected within the five-week period before the
- Priority 3 – (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Andy Gray at extension 7-2651. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description	Code Reference
FS-2	Exterior	Provide a minimum of 36" clearance to and around the fire department connection	
FS-2	Standpipe system	Inspect standpipe system in accordance with nationally recognized standards.	
DEPT EHS	Rm. 314 Fire Extinguishers	Remove strings off of fire sprinkler pipe. Due annual inspection	
DEPT	Nr. 317	Remove items from hallway. Hallways shall NOT be used for storage at any time.	
DEPT	Rm. 318	Remove "household use only" toaster oven	
DEPT		Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	

Responsible Party	Area	Description	Code Reference
DEPT	Rm. 312	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Third floor Stairwell Landing	Remove furniture from landing. These tables and chairs have a tendency to shift around and potentially obstruct the stairwell. They also tend to be a collection point for combustible paper and other material.	
DEPT	Rm. 309B	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Rm. 300	Discard old style fan. The plug actually arced when I pulled on the cord. *The openings are also too large.	
DEPT	Rm. 301	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Rm. 303	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Rm. 305	Remove obstruction to exit. Storage items somewhere else in the room.	
DEPT	Rm. 207	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
RECY	Nr. 216	Fire extinguisher is obscured/obstructed by recycling containers. Relocate containers.	
RECY	Second floor South Wing	Remove combustible recycling containers and other items from this area	
DEPT	Rm. 215	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Nr. 106	Remove combustible recycling containers from hallway.	
DEPT	Rm. 105	Discontinue plugging power strips into each other. They shall plug directly into outlet.	
DEPT	Rm. 103	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable.	
DEPT	Across 101	Install cover over circuit blank in circuit panel.	
DEPT	Rm. 116	Remove all items from fire sprinkler piping.	
FS-2	Rm. 111	Install a non illuminated EXIT sign over exit from this room to the porch.	
FS-2	Basement	Adjust fire door to stairwell to close and latch unaided.	
FS-2		Fire Sprinkler Heads - Check the dates on these heads and replace those over 50 years old, if any. Also several heads have been partially painted. Replace all heads that have paint on either the fusible link or deflector.	
EHS	Wood Shop	Relocate fire extinguisher to near the exterior exit.	
	ANNEX		
DEPT	Rm. 117	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Listed fuse protected power strips are acceptable. Cord is also coming away from the male plug. Repair or discard.	
FS-2		Repair EXIT sign. Bulb burned out.	
DEPT	Rm. 100	Cap all high pressure cylinder not currently in use	
EHS		Replace small fire extinguisher with a 20 lb. unit.	