

**NOTICE OF FIRE SAFETY INSPECTION
OREGON STATE UNIVERSITY**



Facility Inspected: SUPLUS PROPERTY
 Date Inspected: 4/12/2007
 Reinspect Date: 5/17/2007
 Reinspect Time: 9:00 a.m.
 EH&S Rep: Brandon

A fire safety inspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 766-6903. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@ci.corvallis.or.us*

NOTE **Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.**

* *Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).*

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible group(s) and begin corrective action to be completed no later than the reinspection date.

Facility Services Priority Codes:

- Priority 1 – (p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be
- Priority 2 – (p2) items should be corrected within the five-week period before the
- Priority 3 – (p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Andrew Gray (Environmental Health & Safety) at extension 7-7651. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description	Code Reference
EHS	Fire Extinguishers	Inspect and test in accordance with nationally recognized standards.	
DEPT	Warehouse	NE Corner - Improve visibility/accessibility of fire extinguisher	
EHS		NW Corner - Mount fire extinguisher and cabinet	
EHS		SE Corner - Replace fire extinguisher - low pressure	
DEPT		Computer Area - Discontinue use of non fuse protected extension cords in lieu of permanent wiring. Power strips are acceptable	
DEPT	LPG Forklifts	Mount a fire extinguisher on each unit.	
DEPT	eBay processing Area	Discontinue use of non fuse protected extension cords in lieu of permanent wiring. Power strips are acceptable	
DEPT	Upstairs Office	Discontinue use of non fuse protected extension cords in lieu of permanent wiring. Power strips are acceptable	

Responsible Party	Area	Description	Code Reference
FS-2	Reception Area	By Front Door - Repair EXIT sign. Back up power failure.	