

NOTICE OF FIRE SAFETY REINSPECTION

Facility Inspected:	Gill Coliseum
Date Inspected:	9-Nov-06
Reinspect Date:	21-Dec-06
Reinspect Time:	9:00 a.m.
EH&S Rep:	Andy

A fire safety reinspection of the facility listed above was performed by the Corvallis Fire Prevention Bureau. These fire safety deficiencies could result in a fire or jeopardize the safety of those occupying the facility. Please see that these items are corrected immediately. If you have any questions regarding this inspection please phone me at 766-6903. Thank you for your cooperation and support for fire safety. *Jim Patton, Fire Prevention Officer, jim.patton@ci.corvallis.or.us*

<u>NOTE</u>	<u>Deficiencies that are bold and underlined remain uncorrected from the last fire/life safety inspection(s) and should be corrected immediately.</u>
*	<i>Annotates a deficiency identified by OSU Environmental Health & Safety Department. Direct any questions regarding these items to that office (737-2273).</i>

Indicated on the report are items which should be corrected by the Departments (DEPT) that occupy this building, Facilities Services (FS), Environmental Health and Safety (EHS), and Recycling (RECY). Please forward a copy of this report to the responsible groups and begin corrective action as soon as possible.

Facility Services Priority Codes:

Priority 1 –	(p1) items are considered immediate safety hazards and should be corrected within 48 hours of notification if possible. If repairs cannot be made immediately, temporary measures may be taken.
Priority 2 –	(p2) items should be corrected within the five-week period before the scheduled re-inspection.
Priority 3 –	(p3) items are long term fixes that should be either added to an ongoing work list (such as annual testing of building sprinkler systems) or to the capital improvement list for campus upgrades.

The due date is listed at the top of this page. If you have any questions, require additional information, or feel the items have been improperly assigned, feel free to contact Bryan McCampbell at extension 7-2505. If assistance is required from Facilities Services to estimate or correct an item assigned to a Department contact the Customer Service Unit at ext. 7-2969. MS Excel format is available upon request.

Responsible Party	Area	Description
	<u>GENERAL</u>	
FS-2	Knox Box	Provide a key to stairwell sprinkler control valves.
FS-2	EXIT SIGNS	Recommend replacing old outdated (non secondary supply) EXIT signs with LED units with battery backup supply. These units would require significantly less maintenance as they use an LED unit rather than incandescent bulbs which burn out regularly.
DEPT	Stdpipe Cabinets	Cap all 1.5" standpipe outlets.
FS-2	FACP	Provide a key to the fire alarm annunciator panel.
	<u>SECOND FLOOR</u>	
DEPT	Rm.231B	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
FS-2	Rm. 218	Repair broken outlet receptacle.
DEPT	Rm. 219	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.

Responsible Party	Area	Description
DEPT	Nr. 215	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT	<u>Nr. 213</u>	<u>Discontinue use of long extension cord to camera platforms. Provide power in these areas.</u>
DEPT	Nr. 211	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT	Rm. 205	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT	Rm. 201	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT	Rm. 235	Check on operation of fan, may not be functioning properly. Remove all cardboard boxes and other light combustibles and keep this room clear at all times.
	<i>FIRST FLOOR</i>	
EHS	Nr. 136	Replace fire extinguisher. Low Pressure
DEPT	Nr. 129	Remove items from hallway. Hallways shall not be used for storage at any time.
DEPT	Rm. 130	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
FS-2	Nr. 128	Adjust door to basement to close and latch unaided.
FS-2	Rm. 123	Replace cover plate to outlet.
FS-2	Nr. 123	Adjust stairwell doors to close and latch unaided.
EHS	Rm. 118	Remove fire extinguisher on floor.
DEPT	Exterior Cart Storage Shed	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
EHS		Fire extinguisher due.
DEPT	Rm. 112	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT		Plug power strips directly into outlet. Do NOT chain them together.
DEPT	Rm. 108B	Discontinue use of non fuse protected extension cord in lieu of permanent wiring. Lister power strips are acceptable.
DEPT	Nr. 107	Remove items from hallway. Hallways shall not be used for storage at any time.
<u>DEPT</u>	<u>West side storerooms</u>	<u>*Have storage lofts inspected by competent authority to determine suitability, i.e. the Corvallis Building Dept. Storage should not continue until this has been accomplished.</u>
DEPT	<i>Nr. Westside Storage Rms.</i>	<i>NEW - Exit from the court area is blocked by item. These exits shall NOT be blocked or obstructed AT ANY TIME. If this problem persists then storage along this entire hallway shall be prohibited.</i>
DEPT	Nr. 21	Discontinue holding stairwell door open in an unapproved manner.
DEPT	Rm. 18	Secure all high pressure cylinders
FS-2	Right of 12	Adjust stairwell door to close and latch unaided
DEPT	Nr. 6	Remove items from stairwell